



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:						
Company	Patrick D. Collins Resident Agent					
OGM	Steve Demczak Environmental Scientist III					

Inspection Report

Permit Number:	C0070012		
Inspection Type:	COMPLETE		
Inspection Date:	Wednesday, November 04, 2009		
Start Date/Time:	11/4/2009 10:00:00 AM		
End Date/Time:	11/4/2009 3:00:00 PM		
Last Inspection:	Tuesday, August 25, 2009		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's

InspectionID Report Number: 2193

Types of Operations

Date Wednesday, November 18, 2009

Accepted by: jhelfric 12/7/2009

JOHN R. BAZA

Permitee: NEVADA ELECTRIC INVESTMENT CO Operator: NEVADA ELECTRIC INVESTMENT CO Site: WELLINGTON PREPARATION PLANT

Address: 330 E 400 S STE 6, PO BOX 337 SPRINGVILLE UT 84663

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	1,573.50
Total Disturbed	392.00
Phase I	
Phase II	
Phase III	

Mineral Ownership

☐ Federal Underground ☐ State Surface ✓ Loadout County ✓ Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Permittee has received approval to conduct slurry pond inspections on a monthly basis instead of weekly from MSHA.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070012 Inspection Type: COMPLETE

Inspection Date: Wednesday, November 04, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		V	
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		~	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	V		✓	
5.	Explosives		V		
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		✓	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations	✓			
16.a Roads: Construction, Maintenance, Surfacing		✓			
16.b	Roads: Drainage Controls	~			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance	✓		✓	
22.	Other				

Permit Number: C0070012
Inspection Type: COMPLETE

Inspection Date: Wednesday, November 04, 2009

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The Mining and Reclamation Permit will expire on December 10, 2009. The permittee has received a new UPDES Permit #UTG040010. This permit will expire on April 30, 2013. AIR Quality Permit is DAQE-92.

2. Signs and Markers

Identification signs are posted at the gates to the property. Information meets the requirements of the R645 Coal Rules.

3. Topsoil

The topsoil pile shows no signs of wind or water erosion.

4.a Hydrologic Balance: Diversions

The diversions were spot-check and meet the requirements of the R645 Coal Rules.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment ponds were inspected on Aug 24, 2009 with no hazardous conditions were documented. The report is P.E. certified. I inspected the sediment ponds and did not see any hazardous conditions. The MSHA monthly inspection were taken and no hazardous condition reported.

4.c Hydrologic Balance: Other Sediment Control Measures

Several areas throughout the property have new silt fences installed.

4.d Hydrologic Balance: Water Monitoring

Second quarter water data was submitted to the Division.

4.e Hydrologic Balance: Effluent Limitations

There was no discharge for the third quarter.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected on Sept. 30, 2009. The document is P.E. certified. No hazardous conditions were reported.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

21. Bonding and Insurance

The insurance policy will expire on Feb 9, 2010. The policy is afforded by Colony Ins. Co.. The insurance accord form was reviewed and meets Division requirements. The bonding amount is \$5,153,000.